



3/26/02 BP ADD'N OK  
 (MR) PENDING S.S. REPAIR  
 AS SHOWN, OK TO  
 RUN TRENCH PERPENDICULAR  
 TO CONTOUR  
 1-30 DUE TO  
 FLAT  
 SLOPE  
 TOPO PER  
 COUNTY AERIAL

HOUSE LOC.  
 BY JOHN MELLEMA

Addition includes a new family room and replacement kitchen on 1st floor and a replacement bath on 2nd floor. No new bedrooms or baths.

FROM SIGNED RECORD PLAT AND LOCATION SURVEY, EXISTING SET ASIDE HAS DIMENSIONS OF:

$100' \times [0.5 \times (89' + 129')] = 10,700$	SQ. FT.
-	1960
+	500
+	406
+	356
<hr/>	
Adjusted Easement Area	10002 SQ. FT.

LOT 4  
 PLAT # 3808  
 "HIGHLAND LAKE"  
 HOWARD CO., MD

R=640.00

L=190.00

520'

N33°12'13"W 294.43

N60°20'24"E 61.85

50'-0"

UTILITY & DRAINAGE EASEMENT  
 100' TRENCH  
 40,000 SQ. FT. OR 0.9183 AC.

B.R.L.

125.96

PROPOSED REPAIR: RELOCATE TRENCH AND ABANDON ORIGINAL TRENCH

Proposed Repair DRAIN FIELD #1

EXISTING DRAIN FIELD #2

EXISTING DRAIN FIELD #1

CLEANOUT

ADDITION

EXISTING HOUSE

EXISTING WELL

5'-0"

1'-0"

5'-0"

20'-0"

20'-0"

S50°12'48"E

169.72