

FILE INQUIRY NOTES

9512 Linville Ave.

DATE	RESULTS OF REVIEW FOR FILE
11/13/08	<p>Investigated report of a hole forming in citizen's backyard. Telephone call received by 'Desk Sanitarian' Heidi Scott from homeowner at (Terri Suite) at 9512 Linville Ave. in North Laurel. [410-948-5740]</p>
	<p>The owner was home when I arrived (~4:30 pm), and directed me to the backyard where a hole had formed during the day (Thursday, Nov 13). The ^{circular} hole was partly lined with cinder block, and there were 2 pipe 'outlets' at about 4-foot depth. Water level in the hole was at about 10 feet.</p>
	<p>The total depth of the hole was estimated to be about 12-foot. The diameter was measured, 7-foot.</p>
	<p>This is a dry well, of which the cover has just collapsed. The subdivision has been served by public sewer for a number of years. The Health Department has no records for Linville Avenue. Robert Bricker, R.S.</p>
	<p>Homeowner will contract an excavator to fill in dry well. ^{reb}</p>



Disclaimer: Howard County, Maryland assumes no responsibility for the accuracy of this report or the information contained herein or derived therefrom. The user assumes all risks and liabilities whatsoever resulting from or arising out of the use of this information. There are no oral agreements or warranties relating to the use of this report.

-76°50'32"

-76°50'32"

2 pipes out
 of 4' depth
 water bottom approx 11' to 12'
 of 10' diameter



By:
 Office:
 Map Width: 910.00 ft.
 Print Date: 11/13/2008
 Scale: 1 in. = 100 ft.

Howard County

M A R Y L A N D

39°6.33"

39°6.33"



