

LAYOUT 3/10/03 INSP 4 \_\_\_\_\_  
 INSP 2 3/11/03 1:30 INSP 5 \_\_\_\_\_  
 INSP 3 \_\_\_\_\_ INSP 6 \_\_\_\_\_

ISSUE DATE: 3/10/03  
 APPROVAL DATE: 3/11/03

**PERMIT  
INDEXED**

P 518565  
~~205880~~  
 A repair

**ON-SITE SEWAGE DISPOSAL SYSTEM  
 HOWARD COUNTY HEALTH DEPARTMENT  
 BUREAU OF ENVIRONMENTAL HEALTH  
 3525-H ELLICOTT MILLS DRIVE, ELLICOTT CITY, MD 21043**

**03-291014**

Jenkins Brothers \_\_\_\_\_ IS PERMITTED TO INSTALL  ALTER

ADDRESS: 7670 Smith's Private Rd. 21784 PHONE NUMBER: 410-461-9282

SUBDIVISION: Indian Hill LOT NUMBER: 1, Sect 1

ADDRESS: 12595 Indian Hill Road PROPERTY OWNER: Lynn, Edward.

SEPTIC TANK CAPACITY (GALLONS): ex 1000 OUTLET BAFFLE FILTER REQUIRED

PUMP CHAMBER CAPACITY (GALLONS): N/A COMPARTMENTED TANK REQUIRED

NUMBER OF BEDROOMS: 3  $180 \times 3 = 540 \div 2 = 270 \times .31 = 83'$

SQUARE FEET PER BEDROOM: 180

LINEAR FEET OF TRENCH REQUIRED: 750k HOUSE SERVED BY PUBLIC WATER

TRENCHES:	Trench to be <u>2</u> feet wide. Inlet <u>7<math>\frac{1}{2}</math></u> feet below original grade. Bottom maximum depth <u>12</u> feet below original grade. Effective area begins at <u>7<math>\frac{1}{2}</math></u> feet below original grade. <u>6'</u> feet of stone below distribution pipe.
LOCATION:	
NOTES:	Repair called in 3/7/03 for collapsed dry well.

PLANS APPROVED: Steven R. Krieg DATE: 3/10/03

NOTES: PERMIT VOID AFTER 2 YEARS  
 CONTRACTOR IS RESPONSIBLE FOR SCHEDULING A PRE-CONSTRUCTION INSPECTION FOR ALL INSTALLATIONS  
 WATERTIGHT SEPTIC TANKS REQUIRED  
 ALL PARTS OF SEPTIC SYSTEM SHALL BE 100 FEET FROM ANY WATER WELL UNLESS SPECIFICALLY AUTHORIZED  
 MANHOLE RISERS REQUIRED ON ALL SEPTIC TANKS AND PUMP CHAMBERS UNLESS SPECIFICALLY AUTHORIZED  
 CONTRACTOR RESPONSIBLE FOR COMPLIANCE WITH APPLICABLE REGULATIONS, GUIDELINES AND THE TERMS OF THIS PERMIT

**NEITHER THE HOWARD COUNTY COUNCIL NOR THE HEALTH DEPARTMENT IS  
 RESPONSIBLE FOR THE SUCCESSFUL OPERATION OF ANY SYSTEM  
 PERMITTEE RESPONSIBLE FOR OBTAINING FINAL APPROVAL ON THIS PERMIT  
 CALL 410-313-2640 FOR INSPECTION OF SEPTIC SYSTEM  
 DO NOT LEAVE ANY REQUEST FOR INSPECTION ON VOICEMAIL**

P518565

